

Work Order ID 60010

Page 1

Tuesday, June 22, 2010 3:21:56 PM

Item ID: D4043-041

Accept



Setup Start



Revision ID:

Item Name: Rib Assembly

Stop



Start Date: 6/22/2010 Start Qty: 1.00



Cust Item ID:

Required Date: 7/30/2010 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: HDate: 10-06-22

Tooling:

Date:

Run Start



QC: _____

Date: _____

SPC (Y/N):

Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D4043	A

100 Weld per dwg A/R S.S. rod Batch: M10 8775 0.00

Large Fab

Memo 0.00

(1)

Large Fab

- 1- Cut D4043-1 as per dwg D4043
- 2- Drill and chamfer holes as per dwg D4043
- 3- Remove identification markings
- 4- Weld bushing in rib and grind weld flush as per dwg D4043

SAY 10-06-23

(1) DD 10.06.24

110 QC5- Inspect part completeness to step on W/O 0.00



QC

Memo 0.00

Quality Control

SW/64624

(2)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 60010

Tuesday, June 22, 2010 3:21:56 PM



Page 2

Item ID: D4043-041

Accept



Setup Start



Revision ID:

Item Name: Rib Assembly

Stop



Start Date: 6/22/2010 Start Qty: 1.00



Cust Item ID:

Required Date: 7/30/2010 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center ID

120



QC

Quality Control

Operation
Description

QC10- Inspect visual per QSI004- ground welds

Set Up/
Run Hours

0.00

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

S1004104

130



Packaging

Packaging

Identify as per dwg & Stock Location: basket 0.00

Memo

0.00

(D) PD 10.06.24

140



QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/06/24 JJ

CD 10/06/24

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Tuesday, June 22, 2010 3:22:02 PM

Page 1

Work Order ID: 60010



Parent Item: D4043-041



Parent Item Name: Rib Assembly

Start Date: 6/22/2010

Required Date: 7/30/2010

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP RevA: new issue DD 10/01/05 verified by:EC IPP Rev:B as per dwg
revA DD 10.02.18 verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4043-9 		Manufactured	No			100	Each	4.0000	1	1			

Bushing

Location	Loc Qty	Loc Code
WA	4	
56114	4	

M304TS0.500W.049



Purchased

No

Location	Loc Qty	Loc Code
MAT	148.1591158	
114004	0	
114426	9.2647	
114807	138.894416	
MAT018	4.4738	
114004	0.5	
114161	3.9738	
WA	2.62251	
114724	2.62251	

Square Tubing

B60057 ->D RD 10-06-24

S40 10-06-23

2.251789

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

SHOP COPY

RETURN TO

ENGINEERING

UNCONTROLLED COPY


SUBJECT TO AMENDMENT

WITHOUT NOTICE

WORK ORDER

NO. 60010
B810-6-22

ITEM	QTY	P/N	DESCRIPTION
	X	D4043-041	RIB ASSEMBLY
1	1	D4043-1	RIB
2	1	D4043-9	BUSHING



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector


Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8 7 6 5 4 3 2 1



8 7 6 5 4 3 2 1


W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE			By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8 7 6 5 4 3 2 1

D


D

C

C

B

B

D4043-9 BUSHING
RELEASED
 2010-02-16
WJL 60010
NOTES:

- 1) MATERIAL: AISI 303 STAINLESS STEEL ROUND BAR
REF DART SPEC. M303R
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 0.006 lbs

8 7 6 5 4 3 2 1

A

A

DESIGN	RF	DART AEROSPACE LTD
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA
CHECKED	<i>RR</i>	REV. A
MFG. APPR.	<i>DL</i>	DRAWING NO. D4043
APPROVED	<i>WJL</i>	SHEET 4 OF 4
DE APPR.	<i>WJL</i>	TITLE RIB ASSEMBLY
DATE	10.01.29	SCALE NTS

 COPYRIGHT © 2010 BY DART AEROSPACE LTD
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
 NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
 WRITTEN PERMISSION FROM DART AEROSPACE LTD

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE			By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries